

# MODEL T10131 BANDSAW EXTENSION TABLE INSTRUCTIONS

The Model T10131 Bandsaw Extension Table provides additional support for longer workpieces and installs onto the Grizzly bandsaw Models G0531B, G0566B, and G0636XB.

#### **Recommended Tools**

| Hex Wrench 6mm         | 1 EA      |
|------------------------|-----------|
| Wrench/Socket 13mm     | 1 EA      |
| Precision Straightedge | 1         |
|                        | 1         |
|                        | As Needed |
| Shop Rag               | 1         |

#### **Specifications**

| Size   | 203/4" | Χ | 181/8" | x 2" |
|--------|--------|---|--------|------|
| Weight |        |   | 63     | lbs. |

#### **Inventory** (Figure 1)

| A. | Extension Table          | 1 |
|----|--------------------------|---|
| B. | Support                  | 1 |
| C. | Hardware Bag (not shown) | 1 |
|    | —Cap Screws M8-1.25 x 40 | 4 |
|    | —Hex Bolts M8-1.25 x 12  | 4 |
|    | —Flat Washers 8mm        | 8 |
|    | —Lock Washers 8mm        | 4 |




Figure 1. Model T10131 inventory.

#### **Assembly**

1. Remove the protective waxy oil coating from the top of the extension table with a solvent cleaner or degreaser, such as shown in Accessories on Page 2. Avoid chlorinebased solvents, such as acetone or brake parts cleaner that may damage painted surfaces. Always follow the manufacturer's instructions when using any type of cleaning product.



2. Have another person hold the extension wing in place and mount it to the main bandsaw table with the four M8-1.25 x 40 cap screws, lock washers and flat washers, as shown in Figure 2.





Figure 2. Extension table installed.


- 3. Use a straightedge as a gauge and adjust the extension wing up/down until it is flush with the main table above each cap screw, then completely tighten the cap screws.
- 4. Place the straightedge across the extension wing and main table to make sure that the combined table surface is flat.
  - If the outside end of the extension wing tilts down, use a strip of masking tape along the bottom edge of the main table to shim the extension wing up (see Figure 3).



**Figure 3.** Masking tape location for tilting the extension table up.

— If the outside end of the extension wing tilts up, use a strip of masking tape along the top edge of the main table to shim the extension wing down (see Figure 4).

**Note:** After reinstalling the wing, remove all excess masking tape with a razor blade.



**Figure 4.** Masking tape location for adjusting the extension wing down.

**5.** Align the mounting holes on the support plate and the bottom of the extension table, then fasten with four M8-1.25 x 12 hex bolts and flat washers, as shown in **Figure 5**.




Figure 5. Support installed.

Loosen the knob, slide the lower section of the support down and tilt the foot so it is flush with the floor, then tighten the knob.

## **AWARNING**

Do not place workpieces heavier than 100 lbs. on this extension table! Doing so may cause the table to fail, increasing your risk of serious personal injury.

If you need help with your new extension table, call our Tech Support at: (570) 546-9663.

#### **Accessories**

#### G2544—Solvent Cleaner & Degreaser

A great product for removing the waxy shipping grease from your machine during clean up.



**Figure 6.** Cleaner/degreaser available from Grizzly.




#### G9644—12" Precision Straightedge

#### H2675—16" Precision Straightedge

Is your straightedge really straight? These grade 00 heavy-duty stainless steel straightedges are manufactured to DIN874 standards for professional results in setup and inspection work.

### **T10131 Parts Breakdown and List**



| DEE | DADT " | DECODIDATION |
|-----|--------|--------------|
| KEF | PART # | DESCRIPTION  |

| 1 | PT10131001 | LOWER SUPPORT LEG     |
|---|------------|-----------------------|
| 2 | PT10131002 | UPPER SUPPORT LEG     |
| 3 | PT10131003 | FOOT                  |
| 4 | PT10131004 | SUPPORT PLATE         |
| 5 | PT10131005 | CONNECTING SLEEVE     |
| 6 | PT10131006 | KNOB M8-1.25          |
| 7 | PB14M      | HEX BOLT M10-1.5 X 35 |
| 8 | PW04M      | FLAT WASHER 10MM      |

#### REF PART # DESCRIPTION

| 9  | PLN05M     | LOCK NUT M10-1.5       |
|----|------------|------------------------|
| 10 | PB28M      | HEX BOLT M8-1.25 X 60  |
| 11 | PW01M      | FLAT WASHER 8MM        |
| 12 | PS05M      | PHLP HD SCR M58 X 8    |
| 13 | PT10131013 | EXTENSION TABLE        |
| 14 | PSB12M     | CAP SCREW M8-1.25 X 40 |
| 15 | PB06M      | HEX BOLT M8-1.25 X 12  |
| 16 | PLW04M     | LOCK WASHER 8MM        |



Buy Direct and Save with Grizzly® - Trusted, Proven and a Great Value!

Visit Our Website Today And Discover Why Grizzly® Is The Industry Leader!

- SECURE ORDERING
- ORDERS SHIPPED WITHIN 24 HOURS
- E-MAIL RESPONSE WITHIN ONE HOUR

-OR-

# Call Today For A FREE **Full Color Catalog**







